

*vesipumput:*

vesipumppu 590-086 (GMB) Mazda 121 1,1 88-91/1,3 88-6.91/1,3i 16V 91-96, 323 (BF) 1,3 87-89/1,5 87-91/1,6i 85-89, 323 (BG) 1,3 8V 89-91/1,3 16V 89-96, 1,3i 16V 91-96/1,6i 8V 89-91/1,6i 16V 89-96/1,8i 16V 89-95, 323 STW 1,5 STW 87-91/1,6i STW 89-93, 323 (BJ) 1,3i 16V 98-

vesipumppu 590-107 (Bugatti) Audi 50 1,1 74-78, 80 1,3 78-81, VW Derby 1,1 76-81/1,3 76-82, Golf I-II 1,1 74-83/1,3 79-89/1,3i 89-90, Jetta 1,3 80-89, Passat 1,3 2.78-83, Polo I 0,9 76-10.81/1,1 76-10.81/1,3 76-10.81, Polo II 1,05 10.81-86/1,1 10.81-86/1,3i 78-89

vesipumppu 590-119/108 (GMB) Hyundai Accent 1,3 12V 95-1.00/1,5 12V 95-1.00, Elantra 1,5i 91-94, Pony 1,5 90-95, Scoupe 1,5i 90-93/1,5i 92-96/1,5i Turbo 92-96, Mitsubishi Colt I (A150) 1,2 78-8.80/1,2 9.80-84/1,4 78-8.80/1,4 9.80-84/1,4 Turbo 82-84, Colt II (C10) 1,2 84-88/1,5 85-8.88, Colt III (C50, C60) 1,3 12V 88-92/Colt 1,5i 9.88-5.90/1,5i 12V 6.90-92, Colt IV (CA) 1,3i 12V 92-96, Lancer F (A150) 1,2F 83-84/1,4F 83-84, Lancer (C10, C50, C60, C70) 1,2 84-89/1,3 88-90/1,3i 12V 90-92/1,5 84-89/1,5i 88-89/1,5i 12V 90-93, Lancer (CA) 1,3i 93-9.96, Lancer Station Wagon 1,5 STW 85-92, Tredia 1,4 83-84

vesipumppu 590-155 (Bugatti) Lada 1200-1700 1200 71-91/1300 71-91/1500 71-96/1600 77-96/1700i 95-97, Niva 1,6 78-97/1,7i 95-97

vesipumppu 590-156 (Bugatti) Lada Eurosamara 1,5 97-98, Samara 1,1 89-91/1,3 86-96/1,5 88- x2

vesipumppu 590-163 (O.E.M. 616.200.04.20) (Bugatti) Mercedes Benz maasturi G-malli (W460) 300GD 3,0 diesel 80-88, pakettiautot MB100 2,4 diesel 89-, 207D 2,4 diesel (autom.tuul.) 83-92, 307D 2,4 diesel (autom.tuul.) 83-90, 308D 2,4 diesel (autom.tuul.) 83-90, L407D 2,4 diesel (autom.tuul.) 83-85

vesipumppu 590-184 (Airtex) Citroën Berlingo 1,8i 97-, BX 1,6 92-93/1,6i 92-93/1,9i 92-93/1,9GTi 16V (88kW) 88-93/BX 1,9GTi 16V (116kW) 87-93, Evasion 1,8i 97-, Xantia 1,6i 93-12.97/1,8i 93-12.97, Xsara 1,8i 7.97-11.00/1,8i Automatik 7.97-11.00, ZX 1,6i 2.92-95/1,8i 2.92-95/1,8i 16V 94-10.96/1,9i 2.92-93, Peugeot 306 1,8i 93-, 309 1,9GTi 16V 87-92, 405 1,6i 93-97/1,8i 92-97/1,9i Mi16 16V 4WD 87-93, 406 1,6i 95-/1,8i 5.97-, Partner STW 1,8 97-, pakettiautot Partner 190 1,8i 97- x2

vesipumppu 590-193 (Bugatti) Citroën Berlingo 1,9 D 97-, Evasion 2,0i 95-/2,0i Turbo 95-5.96/1,9 TD 95-, Xantia (X1) 2,0i 93-12.97/2,0i 16V 93-12.97/2,0i 16V Turbo 95-12.97/1,9D 1.94-12.97/1,9TD 1.94-12.97, Xantia (X2) 1,9D 1.98-/1,9TD 1.98-, XM (Y3) 2,0 89-93/2,0i 89-94/2,0i 16V 92-7.94/2,0i Turbo 93-4.94/2,1D 89-4.94, XM (Y4) 2,1i Turbo 5.94-10.00/3,0i 16V 5.94-10.00/2,1D 5.94-10.00, Xsara 1,8D 7.97-/1,8TD 7.97-/1,9TD 7.97-, ZX 2,0i 92-95/2,0i 16V 93-95/1,9D 3.94-95/1,9TD 3.94-98, Jumper 2,0i 27 Van 94-/1,9D 27 Van 94-/1,9TD 27 Van 94-, Jumpy 1,9D 96-/1,9TD 96-, Fiat Ducato (230) 2,0i 94-, Scudo 1,9TD 96-, Peugeot 306 2,0i 8V 94-96/306 1,9SLD diesel 2.94-99/1,9SRDT TD 2.94-99, 405 2,0i 92-97/1,9D 2.94-97/1,9TD 2.94-97, 406 2,0i 16V Turbo 97-/1,9TD 95-, 605 2,0i 90-98/2,0i Turbo 92-96/3,0i V6 90-93, 806 2,0i 6.94-/1,9TD 5.97-, Boxer 2,0i 94-, 1,9D 94-/1,9TD 94-, Expert 1,9D 2.96-/1,9TD 2.96-, Partner 190 1,8D 97-/1,9D 97-

vesipumppu 590-198 (Bugatti) Citroën BX 1,8 TD 88-93/1,9 D 10.86-91, Visa 1,6GTI 86-88, Xantia 1,9D 93-12.93/1,9TD 93-12.93, ZX 1,9D 91-2.94/1,9TD 91-2.94, Peugeot 205 1,8D 11.86-89/1,8TD 7.85-92/1,9D 92-93, 305 1,9D 11.86-88, 306 2,0i 16V 94-97/1,9SLD 93-1.94/1,9SRDT turbodiesel 93-1.94, 309 1,9D 11.86-93, 405 2,0i Mi16 16V 93-97/2,0i T16 turbo 4WD 93-97/1,8TD 88-93/1,9D 88-1.94/1,9TD 88-1.94, Rover 418 1,8TD 91-96/1,9D 91-95

vesipumppu 590-210 (GMB) Toyota 4-Runner 2,4D 9.90-93, Land Cruiser 2,4D 90-93, Dyna 100 2,5D 8.88-, Dyna 100 2,8D 89-, Dyna 150 2,8D 88-, Hiace 2,4D 8.89-95, Hiace III 2,4D 4WD 8.89-95, Hiace IV 2,4D 8.95-/2,4TD 8.95-, Hi-Lux 2,4D 89-97/2,4D 4WD 89-97/2,4D 97-/2,4TD 97-

vesipumppu 590-222 (GMB) Saab 90 2,0 85-87, 99 2,0 82-84, 900 2,0 80-91/2,0i 85-91/2,0i 16V 89-93/2,0i Turbo 82-91/2,0i 16V Turbo 84-91/2,0i 16V Turbo 85-93/2,1i 16V 91-94

vesipumppu 590-228 (GMB) Honda Accord (CA4/5) 1,6 12V 11.85-12.89/2,0 12V 11.85-12.89/2,0i 12V 11.85-12.89, Accord Aerodeck 2,0i 85-89

vesipumppu 590-269 (GMB) Opel Ascona B 1,3 79-81, Ascona C 1,3 82-88, Corsa A 1,3 83-89/1,3i 85-89, Kadett D 1,3 79-84, Kadett E 1,3 84-90/1,3i 84-90

vesipumppu 590-282 (Bugatti) VW Multivan 2,5 94-/2,4D 94-, Transporter T4 2,5i 90-7.95/2,4D 90-94/2,4D Syncro 4WD 93-94

vesipumppu 590-283 (Dolz) VW Golf I-II 1,3i 90-91, Golf III 1,4i 8.91-7.95/1,6i 92-7.95, Jetta 1,3i 90-91, Polo II (86C) 1,3i 90-94, Vento 1,4i 92-7.95/1,6i 92-94

vesipumppu 590-294 (GMB) Volvo 240 2,0D 79-81/2,4D 79-91, 260 2,4D 78-81, 740 2,4D/TD 84-92, 740 2,4TD Intercooler 87-92, 760 2,4TD 82-92, 760 2,4TD Intercooler 87-91, 940 2,4TD 90-6.92/2,4TD STW 90-6.92

vesipumppu 590-313 (GMB) Toyota Carina II 1,6 16V 5.87-92, Corolla 1,6 16V 5.87-9.92/1,6i 16V Kat 8.89-9.92/1,6 16V 4WD 88-9.92

vesipumppu 590-316 (GMB) Toyota Avensis 2,0TD 97-, Camry 1,8TD 8.83-86/2,0TD 86-91, Carina 1,8D 82-85, Carina II 2,0D 6.84-93, Carina E 2,0D 5.92-98/2,0TD 1.96-98, Corolla 1,8D 82-4.83, Corolla (E8) 1,8D 5.83-4.87, Corolla (E9) 1,8D 8.87-92, Corolla (E10) 2,0D 92-8.97, Corolla (E11) 2,0D 9.97-2.00

vesipumppu 590-320 (GMB) Opel Ascona C 1,6 81-86/1,8i 82-86, Kadett D 1,6 80-84/1,8 80-84, Kadett E 1,6 84-87/1,8i 84-86, Rekord E 1,8 82-84

vesipumppu 590-321 (GMB) Opel Ascona C 1,6 (16N-OHC) 87-88/1,6 (16SH-OHC) 86-87/2,0i 86-88, Astra F 1,8i 91-8.92/2,0i 91-8.92, Calibra 2,0i 89-8.92, Frontera 2,0i 92-96, Kadett E 1,8i (18SE-OHC) 87-91/1,8 (E18NV/S18NV) 87-91/2,0i 87-90, Omega A 2,0i 86-7.92, Vectra A 1,8 (18SV) 90-92/1,8i (C18NZ) 90-8.92/1,8i (C18NVR) 90-8.92/2,0i (20NE/SEH) 88-92/2,0i (C20NE) 88-8.92

vesipumppu 590-322 (GMB) Opel Ascona C 1,6 87-88/1,6i (C16LZ/NZ) 87-88/1,6i (E16NZ) 87-88, Corsa A 1,4 (14NV) 89-90/1,4i (C14NZ) 89-90/1,6i (C16NZ-OHC) 88-7.90, Kadett E 1,4i (C14NZ-OHC) 89-12.89/1,6 (16SV-OHC) 87-91/1,6i (C16NZ/LZ-OHC) 87-91/1,6i (E16NZ-OHC) 87-91, Vectra A 1,6 (16SV) 88-92/1,6i (E16NZ/C16NZ) 88-7.90

vesipumppu 590-341 (GMB) Nissan Caravan 2,2D (SD22) 79-83, Homer 2,2D (SD22) 79-82, Pick-Up 2,2D (SD22) 80-85/2,3D (SD23) 83-86/2,5D 4WD (SD25) 83-86

vesipumppu 590-358 (GMB) Nissan Micra (K11) 1,0i 16V 93-9.00/1,3i 16V 93-9.00 x2

vesipumppu 590-375 (GMB) Nissan Cabstar 2,3D (TD23) 87-90/2,5D (TD25) 89-92, King 2,3D (TD23) 11.86-89/2,5D (TD25) 89-, Urvan King 2,3D (TD23) 9.86-90/2,5D (TD25) 88-96

vesipumppu 590-388 (GMB) Nissan Almera 2,0D 96-00, Primera 2,0D (P10) 9.90-6.96, Primera 2,0TD (P11) 9.99-, Sunny 2,0D (N14) 92-95

vesipumppu 590-419 (GMB) Mitsubishi Galant 2,3TD 80-84, Pajero I 2,3TD 82-87/2,5TD (LO44/49) 86-12.89/2,5TD (L144/149) 90-4.91, Canter 2,3D (FB213) 83-/2,3D (FB433/436) 86-12.89/2,3D (FB433/436) 90-, L200 2,5D 4WD (4D56) 87-12.89/2,5D 4WD (4D56) 90-12.96/2,5D 4WD (4D56T) 90-12.96/2,5D 4WD (4D56T) 6.95-12.96, L300 2,3D (4D55T) 83-86/2,5D (4D56) 87-12.89/2,5D (4D56) 90-98/Delica 2,5D 4WD (4D56) 92-98, L400 2,5TD (4D56T) 99-

vesipumppu 590-453 (GMB) Toyota Avensis 1,6i 97-, Carina E 1,6i 16V 5.92-98, Celica 1,6i 89-94, Corolla (E10) 1,6i 16V 8.92-97, Corolla (E11) 1,6i 9.97-2.00

vesipumppu 590-550 (Bugatti) Opel Astra F 1,8i 16V (C18XE-DOHC) 93-3.98/1,8i 16V (X18XE-DOHC) 95-3.98/2,0i 16V (C20XE-DOHC) 9.92-3.98/2,0i 16V (X20XEV-DOHC) 95-3.98/1,7D (17D) 93-3.98, Astra G 2,0i 16V (X20XEV-DOHC) 4.98-/1,7TD (X17DTL) 4.98-8.00, Calibra 2,0i 16V (C20XEJ-DOHC) 9.92-95/2,0i (X20XEV-DOHC) 92-95/2,0i 16V Turbo (C20LET-DOHC) 9.92-95, Frontera 2,0i (X20SE) 95-98/2,2i 16V (X22XE-DOHC) 95-98, Omega B 2,0i 16V (X20XEV-DOHC) 5.94-9.99/2,2i 16V (Y22XE) 9.99-, Sintra 2,2i 16V (X22XE-DOHC) 97-99, Vectra A 2,0i 16V (C20XE-DOHC) 9.92-9.95/2,0i 16V Turbo (C20LET-DOHC) 93-95, Vectra A 1,7 D (17D) 9.92-95, Vectra B 1,8i 16V (X18XE-DOHC) 10.95-8.00/2,0i 16V (X20XEV-DOHC) 10.95-01

vesipumppu 590-551 (Airtex) Opel Astra F 1,6i 16V (X16XEL-DOHC) 94-3.98, Astra G 1,6i 16V (X16XEL) 4.98-, Corsa B 1,4i 16V (X14XE-DOHC) 4.93-00/1,6i 16V (C16XE-DOHC) 4.93-96, Tigra 1,4i 16V (X14XE) 95-/1,6i 16V (X16XE-DOHC) 95-, Vectra B 1,6i 16V (X16XE-DOHC) 10.95-01, Zafira 1,6i 16V (X16XE-DOHC) 99-, Combo Van 1,4 (X14XE) 94-

vesipumppu 590-555 (Bugatti) Opel Astra F 1,8i (C18NZ-OHC) 9.92-3.98/2,0i (C20NE-OHC) 9.92-3.98, Calibra 2,0i (C20NE) 9.92-95, Omega A 2,0i (C20NE/20SE) 8.92-94, Omega B 2,0i 8V (X20SE) 5.94-9.99, Vectra A 1,8i (C18NZ) 9.92-9.95/1,8i (C18NVR) /2,0i (C20NE) 9.92-9.95, Vectra B 1,6i (16LZ2-OHC) 10.95-99

vesipumppu 590-581 (Bugatti) Alfa 145 2,0i.e 16V 96-, 146 1,4i.e 16V/1,7i.e 16V 10.96-1.01/2,0i.e 16V 96-1.01, 155 2,0i 16V Twin Spark 96-12.97, 156 1,8i 16V Twin Spark 97-/2,0i 16V Twin Spark 97-, 166 2,0i Twin Spark 98-10.00, Alfa Spider 2,0i 16V 95-, GTV 2,0i 16V 95-, Spider 2,0i 16V 96-, Fiat Barchetta (183) 1,8i 16V 96-, Brava 1,8i 16V 97-, Bravo 1,8i 16V 97-, Marea 1,8i 16V 96-, Punto 130 HGT 1,8i 16V 9.99-

vesipumppu 590-615 (GMB) Ford Mondeo I (GBP) 1,6i 16V 93-8.96/1,8i 16V 93-8.96/2,0i 16V 93-8.96, Mondeo II (BAP) 1,6i 16V 9.96-/1,8i 16V 9.96-9.00/2,0i (NGA-DOHC) 9.96-98/2,0i (NGB-DOHC) 98-9.00

vesipumppu 590-715 (Airtex) Renault Clio 1,4i 98-, Kangoo 1,4 98-, Megane I 1,4e 96-3.99/1,4i 16V 96-3.99, Scenic 1,4i 9.99-

vesipumppu 590-724 (Bugatti) Fiat Brava 1,2i 16V, Bravo 1,2i 16V, Punto I 85 1,2i 16V 4.97-8.99, Punto II 60 1,2i (hihnapyörä 22 mm) 9.99-

vesipumppu 590-778 (GMB) Honda CR-V 2,0i 97-1.99/2,0i 2.99-

vesipumppu 590-782 (GMB) Ford Mondeo II 2,5i 24V 9.96-9.00

vesipumppu 590-793 (Airtex) Fiat Ducato 1,9TD

vesipumppu 590-802 (Industrie Saleri Italo) VW Bora 1,9TDI (AJM) 98-, Golf 1,9TDI (AJM, AUY) 12.98-

vesipumppu 590-809 (Bugatti) VW LT 2,5D (AGX) 93-, LT 2,5TD (AHD) 96-, Transporter T4 2,5i (AAF,ACU) 8.95-/2,4D (AAB) 95-/2,5TD (ACV) 8.95-

vesipumppu 590-841 (Airtex) Opel Astra G Coupe (F07) 1,6 16V 00-05